


















Шкаф Деос ъглов







 Ø6,3x50 mm A1 x 39	 Ø12 mm A2 x 39	 4 mm A3 x 1	 Ø4x16 mm D1 x 20	 Ø4,2x25 mm D2 x 2
 Ø1,6x20 mm F x 99	 H x 1	 I x 2	 Ø5x16 mm L x 16	 M x 4
 Ø15 mm N x 8	 288 mm O1 x 2	 1204 mm O2 x 1	 736 mm P x 1	



Box 1/3


1848x385x3 mm



1850x332x3 mm





1904x400x16 mm



1904x400x16 mm




1904x442x16 mm



Box 3/3

1818x300x16 mm




1828x504x16 mm




Box 2/3


742x395x16 mm



300x299x16 mm




300x290x16 mm




Fittings & Tools



774x774x16 mm




742x70x16 mm






758x758x16 mm







70x507x16 mm



1



2




3

A1 x 8

A2 x 8

A3 x 1



4




A1 x 8




A2 x 8



A3 x 1



5



A1 x 2







A2 x 2







A3 x 1





N x 8




6




⚠ XX=YY≅90°






7






F x 43



 $XX=YY\equiv 90^\circ$



8



9




D1 x 20




D2 x 2




H x 1




I x 2



M.1 x 4



M.2 x 4



P x 1

