









 Ø6,3x50 mm <b>A1 x 18</b>	 Ø12 mm <b>A2 x 18</b>	 4 mm <b>A3 x 1</b>	 Ø15x12 mm <b>B1 x 10</b>	 Ø5x44 mm <b>B2 x 10</b>
 Ø20 mm <b>B3 x 10</b>	 Ø4x16 mm <b>D1 x 16</b>	 Ø8x36 mm <b>G x 48</b>	 <b>N x 4</b>	




### Box 1

120x226x16 mm




1 x2

768x120x16 mm




2 x1

313x70x16 mm



3 x4


360x225x16 mm



4 x2


### Fittings & Tools

313x468x16 mm




5 x2

804x504x16 mm



6 x1

804x500x16 mm



7 x1

1




A1 x 2





A2 x 2




A3 x 1



G x 4



2




A1 x 8





A2 x 8




A3 x 1



G x 4



3




A1 x 4







A2 x 4



A3 x 1




G x 6



4




B1 x 4










B2 x 4



B3 x 4



G x 8



5



A1 x 4




A2 x 4



A3 x 1




B1 x 6




B2 x 6



B3 x 6



G x 26





6



D1 x 16



N x 4

