














 Ø6,3x50 mm <b>A1 x 70</b>	 Ø12 mm <b>A2 x 70</b>	 4 mm <b>A3 x 1</b>	 Ø15x12 mm <b>B1 x 22</b>	 Ø5x44 mm <b>B2 x 22</b>
 Ø20 mm <b>B3 x 22</b>	 Ø4x16 mm <b>D1 x 96</b>	 Ø3x25 mm <b>D2 x 7</b>	 Ø1,6x25 mm <b>F x 251</b>	 Ø8x36 mm <b>G x 67</b>
 <b>K x 8</b>	 <b>N x 5</b>	 845 mm <b>O1 x 2</b>	 <b>Z x 7</b>	




### Box 1/3


847x424x16 mm




847x424x16 mm



594x184x16 mm




594x184x16 mm




Fittings & Tools

### Box 2/3


847x424x16 mm




575x110x16 mm




575x70x16 mm




575x60x16 mm




575x60x16 mm




400x100x16 mm




518x100x16 mm



400x100x16 mm




575x60x16 mm




### Box 3/3


873x297x3 mm





548x406x3 mm








1199x440x16 mm










1199x424x16 mm








1











2




3



4



5




A1 x 4




A2 x 4



A3 x 1



6




A1 x 6



A2 x 6




A3 x 1



x 3



7




A1 x 6



A2 x 6




A3 x 1



x 3

8





A1 x 8




A2 x 8



A3 x 1



9





A1 x 8



A2 x 8



A3 x 1






10














B2 x 6










G x 7






11



12



⚠ XX=YY≅90°



13






D1 x 48




K.1 x 8



K.2 x 8



14



A1 x 32




A2 x 32



A3 x 1



B1 x 16



x 8

15






B2 x 8



B3 x 8








G x 16




x 4

16





x 4



17



!  $XX=YY \cong 90^\circ$



x 8

18





D1 x 24



K.3 x 4



K.4 x 4




x 4

19





D1 x 24



K.3 x 4



K.4 x 4



x 4

20

