













 Ø6,3x50 mm A1 x 14	 Ø12 mm A2 x 14	 4 mm A3 x 1	 Ø3x16 mm D1 x 20	 Ø4x16 mm D2 x 6
 Ø4x30 mm D3 x 9	 Ø8x30 mm E x 2	 Ø1,6x25 mm F x 16	 Ø8x36 mm G x 4	 M x 2
 N x 4	 U x 3	 Y x 2		




Box


450x699x16 mm




450x699x16 mm




880x450x16 mm




848x80x16mm




715x80x16 mm




715x80x16 mm




715x80x16 mm




200x200x3 mm




848x80x16 mm







715x80x16 mm



Fittings & Tools



1



A1 x 4


A2 x 4

A3 x 1



D2 x 3

G x 4

U x 3




2





A1 x 4

A2 x 4




A3 x 1






3



⚠ XX=YY≅90°





4



5




D3x 6





6



M.1 x 2



M.2 x 2







7



D1 x 4



Y x 2








i




D3 x 3




D2 x 3






①




②

Ⓜ







Ex 2



Ø8



1



2

